

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave. St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.15**SOURCE INSPECTION REPORT****Resident Engineer:** Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000038**Date Inspected:** 13-Apr-2007**Project Name:** SAS Superstructure**OSM Arrival Time:** 800**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1530**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**Quality Control Contact:** Lu Jian Hua**Quality Control Present:** Yes No**Material transfer:** Yes No N/A**Sampled Items:** Yes No N/A**Stock Transfer:** Yes No N/A**OK to Cut:** Yes No N/A**Rebar Test Witness:** Yes No N/A**Delayed/Cancelled:** Yes No N/A**Other:** NA**Bridge No:** 34-0006**Component:** NA**Bid Item:** 52, 55**Lot No:** NA**Summary of Items Observed:**

The Caltrans Quality Assurance (QA) Inspector, Mike Hasler was present to observe quality control functions related to welding, testing and fabrication procedures at the ZPMC facility on Changxing Island for the San Francisco Oakland Bay Self Anchored Suspension Bridge.

At 1100 hours ZPMC Quality Assurance (QA) Inspector, Mr. Lu Jian Hua met with Caltrans QA Inspectors, and stated that ZPMC would not be performing any welding today. Mr. Lu also stated that ZPMC would be performing welder qualification side bend re-testing Saturday, April 14, 2007. These were initially tested last Sunday, April 8, 2007 without the Caltrans QA being notified to witness the testing. It was requested that new specimens be cut for additional bend test with the Caltrans QA present to witness.

**Summary of Conversations:**

Noted in the Task Leader journal for this date.

**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

**Inspected By:** Hasler, Mike

Quality Assurance Inspector

**Reviewed By:** McClary, David

QA Reviewer